

School Name: Rankin Elementary		Report Date(s): 1/24/2020	
Date Test Conducted: 11/9/2019		Date Results Received: 11/19/2019	
Number of Faucets Tested: 47			
Lead Results		Copper Results	
Results 15 ppb and above:	2	Results 1.3 ppm and above:	2
Results 10 ppb to below 15 ppb:	1	Detectable results below 1.3 ppm:	44
Detectable results below 10 ppb:	1	Results below detection level:	1
Results below detection level:	43		
Number of Faucets Requiring Remedial Action: 2			
Location of Faucet		Action Taken	Date:
Sample ID: RAN-001-044-DS-P, RAN-001-049-WC-P		<input checked="" type="checkbox"/> Temporarily taken out of service:	11/20/2019
Location Description: RAN-001-044-DS-P: drinking station in room 311 RAN-001-049-WC-P: water cooler in mobile unit #4		<input checked="" type="checkbox"/> Permanently taken out of service:	12/16/2019
		<input checked="" type="checkbox"/> Flush tested:	11/21/2019
		Flush test result: no exceedances	
		<input checked="" type="checkbox"/> Replaced:	12/18/2019
		<input checked="" type="checkbox"/> Retest:	1/11/2020
		Retest result: no exceedances	
		Other: _____	
		<input checked="" type="checkbox"/> Placed back in service on:	1/24/2020
Daily School-Wide Flushing:			
<input type="checkbox"/> Continue with protocol <input checked="" type="checkbox"/> Discontinue flushing protocol (date): 1/24/20 Note: drinking station in room 311 (RAN-001-044-DS-P) was removed 12/16/19; water cooler in mobile unit #4 (RAN-001-049-WC-P) was replaced 12/18/19 and put back in service on 1/24/20			
This is a summary report prepared by Hart & Hickman, PC (H&H). H&H suggests that the full report be referred to with regard to findings, recommendations, and technical limitations for this sampling event.			