

School Name: Southern Elementary School		Report Date(s): 6/28/2021	
Date Test Conducted: 6/18/2021		Date Results Received: 6/24/2021	
Number of Faucets Tested: 5 (only kitchen samples collected, drinking fountains out-of-use)			
Lead Results		Copper Results	
Results 15 ppb and above:	0	Results 1.3 ppm and above:	0
Results 10 ppb to below 15 ppb:	0	Detectable results below 1.3 ppm:	5
Detectable results below 10 ppb:	4	Results below detection level:	0
Results below detection level:	1		
Number of Faucets Requiring Remedial Action: 0			
Location of Faucet		Action Taken	Date:
Sample ID:		<input type="checkbox"/> Temporarily taken out of service:	
Location Description:		<input type="checkbox"/> Permanently taken out of service:	
		<input type="checkbox"/> Flush tested:	
		Flush test result:	
		<input type="checkbox"/> Replaced:	
		<input type="checkbox"/> Retest:	
		Retest result:	
		Other: _____	
		<input checked="" type="checkbox"/> Placed back in service on:	6/28/2021
Daily School-Wide Flushing:			
<input type="checkbox"/> Continue with protocol <input checked="" type="checkbox"/> Discontinue flushing protocol (date): 6/28/21 <input type="checkbox"/> Other (Describe:)			
This is a summary report prepared by Hart & Hickman, PC (H&H). H&H suggests that the full report be referred to with regard to findings, recommendations, and technical limitations for this sampling event.			