

| | | | |
|--|----|---|------------------|
| School Name: Brightwood Elementary | | Report Date(s): | 3/11/2020 |
| Date Test Conducted: 2/15/2020 | | Date Results Received: | 2/24/2020 |
| Number of Faucets Tested: 48 | | | |
| Lead Results | | Copper Results | |
| Results 15 ppb and above: | 1 | Results 1.3 ppm and above: | 0 |
| Results 10 ppb to below 15 ppb: | 0 | Detectable results below 1.3 ppm: | 47 |
| Detectable results below 10 ppb: | 1 | Results below detection level: | 1 |
| Results below detection level: | 46 | | |
| Number of Faucets Requiring Remedial Action: 1 | | | |
| Location of Faucet | | Action Taken | Date: |
| Sample ID: BRW-001-041-DS-P | | <input checked="" type="checkbox"/> Temporarily taken out of service: | 2/25/2020 |
| Location Description: BRW-001-041-DS-P: drinking station in room 324 | | <input checked="" type="checkbox"/> Permanently taken out of service: | 3/11/2020 |
| | | <input checked="" type="checkbox"/> Flush tested: | 2/29/2020 |
| | | Flush test result: no exceedances | |
| | | <input type="checkbox"/> Replaced: | |
| | | <input type="checkbox"/> Retest: | |
| | | Retest result: | |
| | | Other: _____ | |
| | | <input type="checkbox"/> Placed back in service on: | |
| Daily School-Wide Flushing: | | | |
| <input type="checkbox"/> Continue with protocol | | | |
| <input checked="" type="checkbox"/> Discontinue flushing protocol (date): 3/11/20 | | | |
| <input type="checkbox"/> Other (Describe:) | | | |
| This is a summary report prepared by Hart & Hickman, PC (H&H). H&H suggests that the full report be referred to with regard to findings, recommendations, and technical limitations for this sampling event. | | | |