

School Name: Florence Elementary		Report Date(s): 2/13/2020	
Date Test Conducted: 1/11/2020		Date Results Received: 1/21/2020	
Number of Faucets Tested: 61			
Lead Results		Copper Results	
Results 15 ppb and above:	3	Results 1.3 ppm and above:	0
Results 10 ppb to below 15 ppb:	0	Detectable results below 1.3 ppm:	60
Detectable results below 10 ppb:	6	Results below detection level:	1
Results below detection level:	52		
Number of Faucets Requiring Remedial Action: 3			
Location of Faucet		Action Taken	Date:
Sample ID: FLO-001-014-DS-P, FLO-001-024-DS-P, FLO-001-028-DS-P		<input checked="" type="checkbox"/> Temporarily taken out of service:	1/24/2020
Location Description: FLO-001-014-DS-P: drinking station in room P4 FLO-001-024-DS-P: drinking station in room S2 FLO-001-028-DS-P: drinking station in room S5		<input checked="" type="checkbox"/> Permanently taken out of service:	2/13/2020
		<input checked="" type="checkbox"/> Flush tested:	2/1/2020
		Flush test result: no exceedances	
		<input type="checkbox"/> Replaced:	
		<input type="checkbox"/> Retest:	
		Retest result:	
		Other: _____	
		<input type="checkbox"/> Placed back in service on:	
Daily School-Wide Flushing:			
<input type="checkbox"/> Continue with protocol			
<input checked="" type="checkbox"/> Discontinue flushing protocol (date): 2/13/20			
<input type="checkbox"/> Other (Describe:)			
This is a summary report prepared by Hart & Hickman, PC (H&H). H&H suggests that the full report be referred to with regard to findings, recommendations, and technical limitations for this sampling event.			