

<b>School Name: Pilot Elementary</b>		<b>Report Date (s): 08/29/19</b>	
<b>Date Test Conducted: 8/21/2019</b>		<b>Date Results Received: 08/29/19</b>	
<b>Number of Faucets Tested: 31</b> (all GCS identified faucets used for drinking/food preparation)			
<b>Lead Results</b>		<b>Copper Results</b>	
<b>Results 15 ppb and above: 0</b>		<b>Results 1.3 ppm and above: 0</b>	
<b>Results 10 ppb to below 15 ppb: 0</b>		<b>Detectable results below 1.3 ppm: 30</b>	
<b>Detectable results below 10 ppb: 3</b>		<b>Results below detection level: 1</b>	
<b>Results below detection level: 28</b>			
<b>Number of Faucets Requiring Remedial Action: 0</b>			
Daily School-Wide Flushing: <input type="checkbox"/> Continue with protocol <input type="checkbox"/> Discontinue flushing protocol: mm/dd/yyyy <input checked="" type="checkbox"/> Other (Describe: Perform Periodic Flushing)			
This is a summary report prepared by ECS. ECS suggests that the full report be referred to with regards to findings, recommendations, and technical limitations for this sampling event.			

Version \_\_\_\_\_  
Date \_\_\_\_\_