

<b>School Name: Wiley Elementary</b>		<b>Report Date (s): 5/16/19; 8/19/2019</b>	
<b>Date Test Conducted: 5/3/19</b>		<b>Date Results Received: 5/14/19</b>	
<b>Number of Faucets Tested: 22</b> (all GCS identified faucets used for drinking/food preparation)			
<b>Lead Results</b>		<b>Copper Results</b>	
<b>Results 15 ppb and above: 0</b>		<b>Results 1.3 ppm and above: 0</b>	
<b>Results 10 ppb to below 15 ppb: 0</b>		<b>Detectable results below 1.3 ppm: 20</b>	
<b>Detectable results below 10 ppb: 0</b>		<b>Results below detection level: 2</b>	
<b>Results below detection level: 22</b>			
<b>Number of Faucets Requiring Remedial Action: 0</b>			
Daily School-Wide Flushing: <input type="checkbox"/> Continue with protocol <input type="checkbox"/> Discontinue flushing protocol: mm/dd/yyyy <input checked="" type="checkbox"/> Other (Describe: Perform Periodic Flushing)			
This is a summary report prepared by ECS. ECS suggests that the full report be referred to with regards to findings, recommendations, and technical limitations for this sampling event.			