

| | | | |
|---|--|---|--|
| School Name: Lindley Elementry | | Report Date (s): 5/22/19; 8/19/2019 | |
| Date Test Conducted: 5/8/19 | | Date Results Received: 5/21/19 | |
| Number of Faucets Tested: 23 (all GCS identified faucets used for drinking/food preparation) | | | |
| Lead Results | | Copper Results | |
| Results 15 ppb and above: 0 | | Results 1.3 ppm and above: 0 | |
| Results 10 ppb to below 15 ppb: 0 | | Detectable results below 1.3 ppm: 22 | |
| Detectable results below 10 ppb: 0 | | Results below detection level: 1 | |
| Results below detection level: 23 | | | |
| Number of Faucets Requiring Remedial Action: 0 | | | |
| Daily School-Wide Flushing: <input type="checkbox"/> Continue with protocol <input type="checkbox"/> Discontinue flushing protocol: mm/dd/yyyy <input checked="" type="checkbox"/> Other (Describe: Perform Periodic Flushing) | | | |
| This is a summary report prepared by ECS. ECS suggests that the full report be referred to with regards to findings, recommendations, and technical limitations for this sampling event. | | | |