

<b>School Name: Ferndale Middle School</b>		<b>Report Date(s):</b>	<b>5/14/2021</b>
<b>Date Test Conducted:</b>		<b>3/14/2020</b>	<b>Date Results Received:</b>
<b>Number of Faucets Tested:</b>		<b>26</b>	
<b>Lead Results</b>		<b>Copper Results</b>	
Results 15 ppb and above:	1	Results 1.3 ppm and above:	0
Results 10 ppb to below 15 ppb:	0	Detectable results below 1.3 ppm:	25
Detectable results below 10 ppb:	3	Results below detection level:	1
Results below detection level:	22		
<b>Number of Faucets Requiring Remedial Action: 1</b>			
<b>Location of Faucet</b>		<b>Action Taken</b>	<b>Date:</b>
Sample ID: FER-001-028-KF-P		<input checked="" type="checkbox"/> Temporarily taken out of service:	3/25/2020
Location Description: FER-001-028-KF-P: water sprayer in the kitchen		<input checked="" type="checkbox"/> Permanently taken out of service:	3/24/2021
		<input type="checkbox"/> Flush tested: Flush test result:	
		<input type="checkbox"/> Replaced:	
		<input type="checkbox"/> Retest: Retest result:	
		Other: _____	
		<input type="checkbox"/> Placed back in service on:	
<b>Daily School-Wide Flushing:</b>			
<input type="checkbox"/> Continue with protocol <input checked="" type="checkbox"/> Discontinue flushing protocol (date): 3/25/20 <input checked="" type="checkbox"/> Other (Describe: Water sprayer in the kitchen was bagged off and temporarily taken out of use on 3/25/20 until the fixture was permanently removed on 3/24/21. Note that delays in taking the fixture permanently out of service were associated with school closures due to the Covid pandemic.)			
This is a summary report prepared by Hart & Hickman, PC (H&H). H&H suggests that the full report be referred to with regard to findings, recommendations, and technical limitations for this sampling event.			